

**ATTACHMENT XI**  
**PARENT / DAUGHTER COC MASS EVALUATION CHARTS 1-4**  
**(ATTACHMENT WAS ADDED BY THE USER)**

Chart 1  
 Closed Laurel Valley Center Sanitary Landfill, Permit No. 251  
 Sentinel and Performance Well 1,1-Dichloroethane to Chloroethane Ratios (2016-2020)






Chart 3  
 Closed Laurel Valley Center Sanitary Landfill, Permit No. 251  
 Sentinel and Performance Well Trichloroethene to Sum of Dichloroethene Ratios (2016-2020)




Chart 4  
 Closed Laurel Valley Center Sanitary Landfill, Permit No. 251  
 Sentinel and Performance Well Sum of Dichloroethene to Vinyl Chloride Ratios (2016-2020)

